



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

May 9, 2013

Reviewed: 

Mine Name: TRC Mine	Permit Number: S/015/0098
Operator Name: United Mineral	Inspection Date: May 8, 2013
Inspector(s): Wayne Western	Time: 1:15- 1:45 pm
Other Participants: none	Mine Status: ACT
Weather Condition: cool with over cast skies	Last Inspection: NA
Bond Renewal Date: 02/24/2012	Bond Amount: \$30,000
Surface Ownership: SITLA	Mineral Ownership: SITLA
Last Year of Production: 2009	Acreage: 0.38 acres

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Bond/Bond Release	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Annual Fees	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Annual Report	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The bond amount is adequate.

Permit fees were paid in 2013.

The mine is an underground mine. The adits were secure.

The site appeared to be stable.


Conclusions and Recommendations:

The Division should continue to monitor the site on an annual basis.

Directions to Site:

The site is near the Cowboy Mine which is located on the USGS topographic maps.

Inspector's Signature



WHW:

cc: (OPERATOR)

jblale@utah.gov

O:\M015-Emery\S0150098-TRCMine\inspections\lspc-05082013.doc



Sign near entrance



One portal



Second portal



Stockpile